

| ID | Model | Variant | Phone Brand | PhoneName | OperatingSystem | Android Auto | CarPlay | Pairing | Auto Connect Or Disconnect | Signal Strength | Battery | Call Answer From Infotainment | Call Reject From Infotainment | Call Terminate | Handset To Hands free | Hands free To Handset | Call Log Sync | Contacts Download | Play Or Pause | Next Or Previous | Fast Forward Or Fast Rewind | Song Details | Message | Connect Next | Remote Control App | Successful SPP Connection | w3w | WirelessA | Wireless CP | |
|----|-----------|---------|-------------|----------------------|---------------------|--------------|---------|---------|---|-----------------|---------|-------------------------------|-------------------------------|----------------|-----------------------|-----------------------|---------------|-------------------|---------------|------------------|--|------------------------|---------|--------------|--------------------|---------------------------|------|-----------|-------------|------|
| 1 | Tiago BS4 | XT | Panasonic | Panasonic ELUGA NC | Android 6.0 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 2 | Tiago BS4 | XT | Asus | Zenphone 3 | Android 6.0.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 3 | Tiago BS4 | XT | Google | Pixel XL | Android 7.1.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 4 | Tiago BS4 | XT | Motorola | G4 Plus | Android 7.1.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 5 | Tiago BS4 | XT | Lenovo | Lenovo Vive K4 | Android 6.0 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 6 | Tiago BS4 | XT | HTC | Desire 830 32GB | Android 6.0.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 7 | Tiago BS4 | XT | LAVA | Lava X41 | Android 4.4.4 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 8 | Tiago BS4 | XT | Samsung | Samsung Galaxy A9 | Android 6.0.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 9 | Tiago BS4 | XT | Huawei | Honor 6 | Android 6.0 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 10 | Tiago BS4 | XT | Vivo | Vivo V3 Max | Android 5.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 11 | Tiago BS4 | XT | Le TV | Le Tv(Le eco le 2) | Android 5.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 12 | Tiago BS4 | XT | Xiaomi | Redmi Note 4G | Android 6.0 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 13 | Tiago BS4 | XT | Samsung | Samsung Galaxy J2 | Android 6.0.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 14 | Tiago BS4 | XT | Gionee | Gionee S6s | Android 6.0 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 15 | Tiago BS4 | XT | Sony | Sony Xperia XA Dual | Android 6.0.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 16 | Tiago BS4 | XT | Microsoft | Lumia 730 | 10.0.14393.693 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 17 | Tiago BS4 | XT | Vivo | Vivo V5 | Android 5.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 18 | Tiago BS4 | XT | Lenovo | ZUK Z1 | Android 5.1.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 19 | Tiago BS4 | XT | Nexus | Nexus 5X | Android 7.1.1 | NA | NA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Audio doesnt starts until user release the FRW button | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 20 | Tiago BS4 | XT | Samsung | Galaxy S7 Edge | Android 6.0.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL |
| 21 | Tiago BS4 | XT | Google | Nexus 5 | Android 6.1.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 22 | Tiago BS4 | XT | LG | LG G3 | Android 4.4.2 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 23 | Tiago BS4 | XT | Coolpad | Coolpad Note 3 | Android 6.0.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW continue in operation for next song | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 24 | Tiago BS4 | XT | Coolpad | Coolpad Note 5 | Android 6.0.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 25 | Tiago BS4 | XT | OPPO | OPPO F1s | Android 6.0.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 26 | Tiago BS4 | XT | XOLO | Play 8X-1100 | Android 4.4.4 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 27 | Tiago BS4 | XT | Micromax | MI 6 | Android 5.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 28 | Tiago BS4 | XT | Motorola | Moto M | Android 7.1.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 29 | Tiago BS4 | XT | Motorola | Moto G Turbo | Android 6.0.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 30 | Tiago BS4 | XT | Samsung | Galaxy ON 7 Pro | Android 6.0.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 31 | Tiago BS4 | XT | Samsung | Galaxy A5 | Android 6.0 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 32 | Tiago BS4 | XT | HTC | HTC one X9 | Android 6.0.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 33 | Tiago BS4 | XT | Motorola | Moto G turbo | Android 6.0.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 34 | Tiago BS4 | XT | MI | MI 5 | Android 4.4.4 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 35 | Tiago BS4 | XT | Samsung | s7 edge | Android 7.1.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | FFW/FRW is not working | ✓ | NA | ✗ | NA | ✓ | NULL | NULL | NULL | |
| 36 | Tiago BS4 | XT | Oppo | F1s | Android 5.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 37 | Tiago BS4 | XT | LG | G6 | Android 7.0 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 38 | Tiago BS4 | XT | Motorola | G5 | Android 7.0 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 39 | Tiago BS4 | XT | One Plus | One Plus 3T | Android 7.1.1 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 40 | Tiago BS4 | XT | Gionee | A1 | Android 7.0 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 41 | Tiago BS4 | XT | Huawei | Honor 8 Lite | Android 7.0 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 42 | Tiago BS4 | XT | HTC | U Ultra | Android 7.0 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 43 | Tiago BS4 | XT | Oppo | F1s | Android 5.2 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 44 | Tiago BS4 | XT | LG | G4 | Android 7.0 | NA | NA | ✓ | on BT off and on , phone is not autoconnect to HU | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Fast fwd/rewind not happening for phone's default music player) | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 45 | Tiago BS4 | XT | Lenovo | K8 Note XT1902-3 | 7.1.1 (NMB26.54-94) | NA | NA | ✓ | Manual Connection | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Music playback fast forward and rewind functions cannot be controlled using the Head Unit. | ✓ | NA | ✓ | NA | ✗ | NULL | NULL | NULL | |
| 46 | Tiago BS4 | XT | Lenovo | K8 Plus XT1902-2 | 7.1.1 (NMC26.74-45) | NA | NA | ✓ | Manual Connection | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Music playback fast forward and rewind functions cannot be controlled using the Head Unit. | ✓ | NA | ✓ | NA | ✗ | NULL | NULL | NULL | |
| 47 | Tiago BS4 | XT | LG | V30+ H930DS | 7.1.2 (V10F-IND-XX) | NA | NA | ✓ | Manual Connection | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Music playback fast forward and rewind functions cannot be controlled using the Head Unit. | ✓ | NA | ✗ | NA | ✗ | NULL | NULL | NULL | |
| 48 | Tiago BS4 | XT | Nokia | 3 8.0.0 (00WW_3_310) | Android 8.0.0 | NA | NA | ✓ | Manual Connection | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Music playback fast forward and rewind functions cannot be controlled using the Head Unit. | ✓ | NA | ✓ | NA | ✗ | NULL | NULL | NULL | |
| 49 | Tiago BS4 | XT | Nokia | 5 8.1.0 (00WW_5_600) | Android 8.0.0 | NA | NA | ✓ | Manual Connection | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | Music playback fast forward and rewind functions cannot be controlled using the Head Unit. | ✓ | | | | | | | | |

